

# PG0002-BOSCH-ME7.4.5-PSA-标致雪铁龙

1. 打开 KTAG 软件, 点汽车



2.找到标致,找到 307,找到 ME7.4.5,点 OK





www.dtaes.cn



# 3.进入,往下拉

	Family 25	Kr
	Warnings	
To use this protocol of comn be done with great care and After opening the ECU and be <u>advised to reconnect the uni</u> To use this protocol you also more wires to the programm Incorrect or poorly made co Under no circumstances we i	nunication you have to remove and open the ECU. I caution to avoid damaging the ECU beyond repair. efore proceeding with reading and/or programmin to the vehicle and start the engine, to make sure need to connect to the ECU connector through a c ing pads. nnections and solderings may damage the ECU, oft shall be liable for any damage caused to the ECU d	It is a risky operation, to g, <u>you are strongly it still works</u> able, and solder one r en beyond repair uring the openic due to
connections and soldering the BY USING THIS PROTOCOL, YA AND CONDITIONS, YOU RELIE ANY COMPENSATION.	at do not comply with the instructions provided in DU CONFIRM YOUR FULL AND UNCONDITIONAL ACCE WE US FROM ANY RESPONSABILITY AND RENOUNCE	this manual. PTANCE OF STERMS TO ALL RISS TO CLAIM
	Recommendation	
1. Remove the ECU from the	ne vehicle;	
<		>
	Cancel OK	

### 4. 找到 Instructions, 点 here







# 5.进入,往下拉



## 6.进入,往下拉,找到并点 Direct connection







#### PG0002

### 7.进入 Direct connection, 往下拉



### 8.进入 Direct connection, 往下拉, 找到 CNF1 和 BOOT



大唐汽车电子



#### 编程指南

#### PG0002

# 9.往下拉找到接线图 (K-B4 右测第 2 个), 接好线之后, 点 OK

as still	PIN F4,H2 =		the statement of the statement
PIN H4 = GND	PINB	4 = K-LINE	
-	Pin F4.H2	Red	+12V
-	Pin H4	Black	Ground
-	Pin B4	Yellow	K-Line
-	Soldered wire	Gray with alligator clip	BOOT
-	Soldered wire	Blue with alligator clip	CNF
	wires before re	einstalling the ECU on t	ehicle.

### 10.进入编程页面, Backup 是全部备份, Restore 是全部恢复



### Raed 是读程序, Write 是写程序





#### 编程指南

#### PG0002

11.取消勾选 Backup 可以单独读,取消勾选 Restore 可以单独写



## 11. Backup 备份读的文件如下

名称	修改日期	类型	大小
ME745-0261S08589-1037525138-9679089480-P856	2022/10/3 15:36	文件	363 KB
🚯 ME745-0261S08589-1037525138-9679089480-P856.EPR	2022/10/3 15:36	EPR 文件	4 KB
ME745-0261S08589-1037525138-9679089480-P856.MPC	2022/10/3 15:36	MPC 文件	832 KB

363kb 文件是二合一文件,包含 EPR 文件和 MPC 文件 Restore 恢复写 363kb 文件,等于同时写 EPR 文件和 MPC 文件

大唐汽车电子

www.dtaes.cn

v2.0 2022-10-19



#### 编程指南

PG0002

12.针脚位置说明: B4-K线, 竖着 B列, 横着第4排



### 插头里面有字: ABCDEFGH/1234

13.编程数据说明:后写的数据,会覆盖先写的数据

